

INSPECTION SOFTWARE



CargoINS

REDIFING CARGO INSPECTION

CargoIns is an innovative real-time application designed to revolutionize cargo inspections. Known for its speed, ease of use, and efficiency, CargoIns offers the best proof of the condition of your goods.

The platform is trusted by industry leaders like Tata Steel, Logistec, and FedNav to meet their inspection needs and reduce cargo claims.



WHAT IS UNIQUE ABOUT CARGOINS?

01

PERFORMING THE INSPECTION ONLY WITH YOUR SMARTPHONE

02

ALL COLLECTED DATA IS AVAILABLE IN REAL-TIME ON OUR WEBSITE

03

CREATING CUSTOMIZED CHECKLISTS THAT CAPTURE THE ESSENCE OF THE TASK AT HAND

04

ENTERING ANY DAMAGES RIGHT ON THE SPOT

05

CREATING A DIGITAL REPORT WITH A FEW CLICKS

06

TRACKING OF THE WEATHER CONDITIONS

BENEFITS

Speed



Conduct inspections using only your smartphone. No more paper records to input into Excel. Share the information collected during inspections in real time and record any damages with detailed photos and descriptions, ensuring accurate documentation that simplifies the reimbursement process.

Efficency



Create clear and concise digital reports with just a few clicks, saving time and simplifying information sharing. Send emails directly from the platform, attaching photos, reports, and any other necessary documents for smooth and efficient communication with your clients and colleagues.

Business Insights



Enhance planning with statistics, pivot tables, and insights. Turn your data into valuable information, enabling you to make informed trading decisions based on historical factors related to terminals, cargo, and vessel movements.

CargoINS IS DESIGNED FOR

01

INSPECTORS

02

TERMINAL OPERATORS

03

CHARTERERS

04

DEMURRAGE DEPARTMENTS

05

MARINE ASSURANCE / RISK AND LOSS DEPARTMENTS

06

SHIPPERS AND RECEIVERS

INSPECTING YOUR CARGO IN A COUPLE OF SIMPLE STEPS




- Scan a barcode
- Enter damages
- Take pictures & video
- Save it




Once the piece is saved, all data can be accessed from anyone who has the privilege, anywhere in the world.

INSPECTING YOUR CARGO IN A COUPLE OF SIMPLE STEPS



SCAN THE BARCODE



INSERT THE DAMAGE



TAKE A PICTURE AND SAVE

WEB-BASED MANAGEMENT PANEL



Username

Email Address

Password

Enter Password



 Sign in

INITIAL SCREEN

The screenshot shows the initial screen of the CargoINS application. The interface includes a header with the logo, a search bar, and a user profile. A left sidebar contains a navigational panel with menu items: Orders, Registry, Operation registry, and Inventory. The main content area features a filter section with dropdown menus for Status, Customer, and Place, and a table displaying an orders list. Red arrows and labels highlight these key components.

Annotations:

- drop-down filters:** Points to the Status, Customer, and Place filter menus.
- search bar:** Points to the search input field.
- navigational panel:** Points to the sidebar menu.
- orders list:** Points to the table of orders.

Header: CargoINS | Search: Type to search items/orders (3 chars min)... | Admin





Filter Section:





- Status: Incoming, In progress, Reporting, Closed, Canceled
- Customer: Select, Sonoco, Tata Steel, Thyssenkrupp
- Place: Select, Burns Harbor, IN, USA, Cleveland, OH, USA, Hamilton, ON, Canada, Iskenderun, Turkey, Talbot, WS, UK





Orders List:





ID	Description	Customer	Status	Cargo	Place	Start	End
SON-05-23	MV Irma	Sonoco	IN PROGRESS	1000.00 M/T of pulp 2000.00 M/T of wire rod	Hamilton, ON, Canada	2023-08-10 08:00	
TKS-01-24	MV Federal Yoshino	Thyssenkrupp	IN PROGRESS	1100.00 M/T of skidded steel coil 4000.00 M/T of wrapped steel coil	Burns Harbor, IN, USA	2024-04-22 08:00	

NAVIGATIONAL PANEL

- Orders 
- List
- New
- Stats
- Pivot
- Registry 
- Operation registry 
- Inventory 







- Orders 
- Registry 
- Customers
- Receivers
- Users
- Countries
- Places
- Operation registry 
- Inventory 

- Orders 
- Registry 
- Operation registry 
- Products
- Operation types
- Where
- Checklist types
- Questions
- Inventory 

- Orders 
- Registry 
- Operation registry 
- Inventory 
- Inventory
- Shipments
- Warehouses
- Users

NAVIGATING ORDERS

1 to 2 of 2 30

ID	Description	Customer	Status	Cargo	Place	Start	End	
SON-05-23	MV Irma	[REDACTED]	IN PROGRESS	1000.00 M/T of pulp 2000.00 M/T of wire rod	Hamilton, ON, Canada	2023-08-10 08:00		  
TKS-01-24	MV Federal Yoshino	[REDACTED]	IN PROGRESS	1100.00 M/T of skidded steel coil 4000.00 M/T of wrapped steel coil	Burns Harbor, IN, USA	2024-04-22 08:00		  

TKS-01-24 - MV Federal Yoshino - Burns Harbor, IN, USA

Menu: Main | Cargo | Times | Attachments | Customer users

general info

Main info

Customer	Customer ID
Thyssenrupp	LT152673
Type	Order ID
Discharging	TKS-01-24
Description	Place
MV Federal Yoshino	Burns Harbor, IN, USA

[Delete order](#)

TKS-01-24 - MV Federal Yoshino - Burns Harbor, IN, USA

Setup: Checklists | Piece inspection | Survey photos | Gallery

inspection data

Users

Select users: [Add](#)

Added employees: Added inspectors:

Services

"Where" in piece inspection: [Set](#)

Checklists

Select checklist: [Add](#)

Added checklists:

- Match opening
- Discharging Survey Skidded Steel Coils

Copyright © 2021. All right reserved.

TKS-01-24 - MV Federal Yoshino - Burns Harbor, IN, USA

Type [edit](#) [share](#)

reporting

→ Next

Type

Normal report


PIECE INSPECTION

Filter: Inspected | Product: All | Issue type: All | Where: All | Receiver: All | Actions

1 | 30 | 3 pieces

Edit	Number	Product	Receivers	Other details	Issues	Delete
<input checked="" type="checkbox"/>	843938111	skidded steel coil	Steel Warehouse	bl no: 90783CEANHASP215	P1 OD Torn Where: Dockside Note: about 3 in	
<input checked="" type="checkbox"/>	07465102	skidded steel coil	Ford	bl no: 90783CEANHASP217	M6 Dent Where: Discharging	
<input checked="" type="checkbox"/>	0800331	skidded steel coil	Crown Cork & Seal	bl no: 90783CEANHASP207	M2 Metal Exposed Where: Onboard Note: small tear	

Edit photo caption



Caption

Rotate **Fullscreen** **Save** **Cancel**

skidded steel coil | Crown Cork & Seal | bl no: 90783CEANHASP207 | **M2 Metal Exposed**
Where: Onboard

CHECKLIST

Setup Checklists Piece inspection Generic photos Gallery

Add checklist

View	Name	Checklist type	Questions	Delete
🔍	abc	Hatch opening	2 / 12	🗑️
🔍	xyz	Discharging Survey Skidded Steel Coils	2 / 3	🗑️






Type to search items/orders (3 chars min)...

Admin

TKS-01-24 - MV Federal Yoshino - Burns Harbor, IN, USA


Setup Checklists Piece inspection Generic photos Gallery

Back


Edit	Question	Answer	Note	Delete
✎	Cargo Holds / Hatch Covers Deficiencies	No	No holds/covers deficiencies noted.	🗑️
	 2024-04-21 12:25 🗑️	 2024-04-21 12:25 🗑️		
+	Signs of Water Ingress / Wetting	No	No signs of water ingress or wetting found.	🗑️
	 hold 3 2024-04-21 12:27 🗑️	 hold 4 2024-04-21 12:27 🗑️	 hold 2 2024-04-21 12:27 🗑️	
+	Cargo Shifting			

Fill in the answer





CHARTS






COMPARATIVE CHARTS






CHARTS






CARGOINS APP



INSPECTING CARGO



CREATING CHECKLISTS



CREATING A REPORT

TKS-01-24 - MV Federal Yoshino - Burns Harbor, IN, USA

Type

→ Next

Type

- ✓ Normal report
- Excel report
- specific report

Type Checklists Piece inspection Piece infos Overview Ordering Generate

← Prev → Next


Select	Name	Checklist type
1	abc	Hatch opening
×	xyz	Discharging Survey Skidded Steel Coils

Type Checklists Piece inspection Piece infos Overview Ordering Generate

← Prev → Next

Condition: With issues Product: All Issue type: All Where: All Receiver: All

Select	Number	Product	Receivers	Issues
✓	9125061	wrapped steel coil	DS Containers	M8 Metal Buckled Where: Discharging M9 Gouge Where: Discharging



Type Checklists Piece inspection Piece infos Overview Ordering Generate

← Prev → Next

Information to be inserted in the piece tables:

- 1 ID/Code/Number
- 2 Product
- 3 Issues

CREATING A REPORT

Type Checklists Piece inspection Piece infos Overview Ordering Generate

← Prev → Next

Inspection overview

Lorem ipsum dolor sit amet, consectetur adipiscing elit, sed do eiusmod tempor incididunt ut labore et dolore veniam, quis nostrud exercitation ullamco laboris nisi ut aliquip ex ea commodo consequat. Duis aute irure d esse cillum dolore eu fugiat nulla pariatur. Excepteur sint occaecat cupidatat non proident, sunt in culpa qui laborum.

Inspection summary

Lorem ipsum dolor sit amet, consectetur adipiscing elit, sed do eiusmod tempor incididunt ut labore et dolore veniam, quis nostrud exercitation ullamco laboris nisi ut aliquip ex ea commodo consequat. Duis aute irure d esse cillum dolore eu fugiat nulla pariatur. Excepteur sint occaecat cupidatat non proident, sunt in culpa qui laborum.

Type Checklists Piece inspection Piece infos Overview Ordering Generate

← Prev → Next

- 1 Report overview
- 2 Summary of issues found in checklist
- 3 Summary of issues found in piece inspection
- 4 Review of damaged pieces

TKS-01-24 - MV Federal Yoshino - Burns Harbor, IN, USA

Type Checklists Piece inspection Piece infos Overview Ordering Generate

← Prev

Generate

PRICING

Prices

Customer will receive 1 month free trial.
Prices and tiers vary based on your business needs.

Customer Satisfaction

The platform is fully customizable.
The team is available for features software integration or white label solutions.



Move Faster, Work Easier

Connect with us.

 +1 216-235-1374

 info@cargoins.tech

